PART III - LIST OF DOCUMENTS, EXHIBITS, AND OTHER ATTACHMENTS SECTION J – LIST OF ATTACHMENTS

ATTACHMENT J-8: CAMPAIGN CROSSWALK TO PWS SECTIONS

Campaign Title	PWS Elements	PWS Descriptions	Number of SWMUs/AOCs
Chromium Interim Measures and Characterization	C.10.1 – C.10.6	Chromium Groundwater Interim Measures	1
Historical Properties Completion		Remaining high-angle remediation and sites on Los Alamos County or Private Property	84
	C.11.2.1,	Gauje/Barrancas/Rendija,	(-)
	C.11.2.3,	Bayo Pueblo	(7)
	C.11.2.2,	Upper Los Alamos,	(31) (46)
	C.11.2.5	Middle Los Alamos	(40)
	0.11.2.0	SWMUs and AOCs in TA-0 and TA-1	
RDX Characterization	C.9.1	RDX Surface Water completion	2
		and Groundwater characterization	
Supplemental Investigation Reports (SIR)		Supplemental Investigation Reports and Certificates of Completion for the following Aggregate Areas:	
	C.11.2.25,	• S-Site,	62
	C.11.2.21,	Potrillo and Fence Canyons,	15
	C.11.2.16,	Threemile Canyon,	19
	C.11.2.26,	TA-49 Inside Nuclear Environmental Site (NES),	9
	C.11.2.27,	TA-49 Outside NES,	3
	C.11.2.18,	 Canon de Valle TA-14, 	20
	C.11.2.22,	North Ancho Canyon,	2
	C.11.2.7,	 Lower Sandia Canyon, 	16
	C.11.2.11, C.11.2.8, 9,	 Upper Canada del Buey, 	48
	and 10.	andMortandad Canyon.	28
TA-21 D&D and Cleanup	C.11.2.04	DP Site Aggregate Area including	41
		DP East, Site Cleanup activities,	
		buried waste line excavation,	
		corrective actions at TA-21-	
		004(b)-99, demolition of TA-21-	
		257, and demolition of DP West and buried contaminated soils	
RDX Remedy Campaign	C.9.2-5	CMIP, Implementation, Permitting,	(2 above)
TON Romody Campaign	0.0.2 0	and Remedy Operations	(2 above)
Known Cleanup Sites		Sol removal from 20 sites from	20

(Above SSLs)		previous investigations	
General's Tanks (MDA-	C.12.2.1	MDA-A General's Tanks Removal	2
A)		Action	
,		[This is a radiological-only DOE	
		campaign and is not listed in the	
		2016 Consent Order, Appendix	
		C.1	
MDAs -A & -T Remedy	C.12.2.1	Pits and Trenches	28
merio ri a i riemeay	01121211	Characterization and MDA-A	20
	C.12.2.6	Corrective Measures Evaluation	
	01121210	Report and	
		MDA-A Remedy Project	
		MDA-T Remedy Project	
		And TA-21-257 post demolition	
		accessible SWMUs and AOCs	
Chromium Final Remedy	C.10.7-9	Chromium Groundwater	N/A
		Remediation	,, .
Southern Boundary	C.11.2.23,	South Ancho Canyon Aggregate	59
Protection	,	Area	
	C.11.2.24,	Chaquehui Canyon Aggregate	
	,	Area	
	C.11.2.20	Lower Water Canyon Aggregate	
		Area	
MDA-C	C12.2.2	MDA-C	1
Sandia Canyon	C.11.2.6,	Upper Sandia Canyon Aggregate	49
Watershed		Area,	
	C.11.2.7,	Lower Sandia Canyon Aggregate	
		Area,	
	C.11.2.8,	Upper Mortandad Canyon	
		Aggregate Area,	
	C.11.2.9,	Middle Mortandad and Ten Site	
		Canyons Aggregate Area PMR.	
	C.11.2.10,	Lower Mortandad and Cedro	
		Canyons Aggregate Area PMR,	
	C.11.2.11,	Upper Canada del Buey Canyon	
		Aggregate Area,	
	C.11.2.12,	Middle Canada del Buey Canyon	
		Aggregate Area PMR,	
	C.11.2.13	Lower Mortandad and Lower	
		Canada del Buey Canyons	
		Aggregate Area PMR	
Pajarito Watershed	C.11.2.14,	Starmer/Upper Pajarito Canyons	167
		Aggregate Area,	
	C.11.2.15,	Twomile Canyon Aggregate Area,	
	C.11.2.16,	Threemile Canyon Aggregate	
	0.44.0.1=	Area,	
	C.11.2.17	Lower Pajarito Canyon Aggregate	
	0.44.0.45	Area	2-2
Upper Water Watershed	C.11.2.18,	Canon de Valle Aggregate Area	253
	i	TA-15,	

	T	Ta	T
		Canon de Valle Aggregate Area TA-16,	
		· ·	
		Canon de Valle Aggregate Area	
	_	TA-14,	
	C.11.2.19	Upper Water Canyon Aggregate	
		Area	
	C.11.2.25	S-Site Canyon Aggregate Area	
MDA-AB	C.12.2.7,	MDA-AB	12
	C.11.2.26,	TA-49 Inside NES	
	C.11.2.27	TA-49 Outside NES	
MDA-H Remedy	C.12.2.4	MDA-H	1
MDAs –G& -L Remedy	C.12.2.3,	MDA-G	12
-	C.12.2.5	MDA-L	
		MDA-L Interim Measure Soil	
		Vapor Extraction (SVE) System	
Non-Campaign Base	C.3,	Programmatic Requirements	N/A
Program Activities		distributed across the programs,	
	C.7	Monitor Surface Water Gage	
		Stations	
	C.5	Monitor Groundwater per IFGMP	
		and Other Programs	
	C.7	Monitor Early Notification System	
		for BDD	
	C.6	Drilling (Install Additional	
		Groundwater Wells Required for	
		Other Activities)	
	C.7	Monitor IP Sampling	
	C.8	Individual Permit Surface Water	
	0.0	Corrective Actions	
		Corrective Actions	